



iSCSI to SATA Storage Subsystem Firmware Release Note

Release Date: 2009/05/17

Release model: iAge820-iSCSI, mAge208U20-iSCSI, mAge316U20-iSCSI

Version: 2.3.4_200904161100

Bug fixed:

1. 1. Translate English "Dedicated spares" into German, French, Russian, and Simplified Chinese.
2. 2. Naming UDV, with special characters, ex, "udv&" will make web UI hang at "Loading".
3. 3. In console UI, the company & product name disappeared after checking PD's 'More Information'.
4. 4. It's invalid to attach LUN over 255 in Console UI, and it pops up 'No LUN available'.
5. 5. In the web UI, "/System config/SNMP", the default events level are changed to "WARNING" and "ERROR" instead of "INFO".

Feature change:

1. 1. Display hard drives firmware versions on Web/Console UI.
2. 2. Add code to let user create UDV without RAID initialization in RAID 3/5/6/30/50/60.

Known Issue:

None.

Companion software:

1. 1. QCentral/RAIDFinder 1.0.0 (Build 10)
2. 2. mkfw 1.10